

CORNER RECORD

COUNTY OF Mono T. 1 S R. 23 E MD MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER ☒ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐
 CORNER IDENTIFICATION — DATE OF VISIT November 30 1976



Stamped

T 15, 233E
 $\frac{1}{4}$ 89
 516
 REPAID 11-16

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☒ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1 1/2" ISIP 25' from corner with two small pieces of fence line
 as per 1880 USGPO Notes. Record shows 30" (1100 40") Eas. 22 (1100 40")
 "Hole" Boring 3' 20" to 12' from p.p. — Fts OK —

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 2" inside diameter x 3' iron pipe, with 2 1/2" California
 Division of Highway "E" Cap 2' to top of 1" pipe,
 beside found 1 1/2" ISIP & stamped as "Later note."
 Lined for 1/2" ISIP 25' — 25' dist. from new
 cap to 03' from corner.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐
 STATIONS USED: NGS (USC & GS) ☒ STATE ☒ COUNTY ☐ OTHER ☐ STATION _____ STATION _____
 ZONE 3 ELEVATION _____ NORTHINGS (Y) 501,386.41 EASTINGS (X) 2,463,579.21

SKETCH: (Include reference tie or witness points, remarks and topo of area)

"Barnyard Tree"
 Found 40" diam.
 Ring w/ old original
 Boring 3' 20" to 12'
 12' from p.p.

9 chains
 To E.S. corner of 1100 40"
 # Found (Dist)

"Barnyard Tree"
 Found 40" Pine with
 original glass & 3' from p.p.
 Forest Service corner 1100 40"
 1100 40" Intal 1912

Set 2" inside diameter x 3' iron pipe

Found 1 1/2" ISIP
 25' from corner.

Found 1 1/2" ISIP
 25' East of Cor.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY
 DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON November 30 1976

SIGNED: [Signature]
 L.S. or R.C.E. No. [Signature]

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Jan 25 1977
 AND EXAMINED AND FILED Jan 26 1977

BY: [Signature]
 TITLE: 1100 40" 1912

DOCUMENT No. 1528-16-2

STATEMENT ON BACK OF SHEET