


**CORNER RECORD**

DPD-3011 (NEW 11/93)

Document Number 1N26-16-11City of \_\_\_\_\_ County of MONO, CaliforniaBrief Legal Description PROPERTY CORNER IN SECTION 16, T.1N., R.26E., M.D.M.**CORNER TYPE**

Government Corner ☐ Control ☐  
 Meander ☐ Property ☒  
 Rancho ☐ Other ☐  
 Date of Survey 4-18-00

**Coordinates (Optional)**

N. 661650.580  
 E. 2122400.492  
 Zone 3 NAD: '27 '83 ☒  
 NAD-83 Epoch (1986)  
 Elevation \_\_\_\_\_

Corner — Left as found ☒ Found and tagged ☐ Established ☐ Reestablished ☐ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

\* SEE CALTRANS RIGHT-OF-WAY MAP  
MND-395-50.58/81.394 PAGE 13  
FOR MORE INFORMATION

A description of the physical condition of the monument as found and as set or reset: FOUND REBAR  
WITH PLASTIC CAP "LS 4587" FLUSH.

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with  
 the Land Surveyors' Act on 4-18-00 49.


Signed Karl A. Riesen L.S. or R.C.E. Number 7285  
 For the State of California  
 Department of Transportation

**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received MAY 1, 2000 and examined  
 and filed MAY 5, 2000

Signed John K. Beck Title DEPUTY MONO COUNTY SURVEYOR  
EXP. 6-30-00

County Surveyor's Comment \_\_\_\_\_

1N26-16-11